

CERTIFICATE OF ANALYSIS

MAIDAMAX (M) SDN BHD
Lot. 10-13, Jalan PKNK 1/2,
Kawasan Perusahaan Sungai Petani,
08000 Sungai Petani, Kedah, Malaysia.
Tel : 04-4414 644 Fax : 04-4414 649
Attn : Mr Samuel Saw

Certificate No : CN/nCML0179/0713
Sample Log Code : nCML0212/0713
Sample Received Date : 23-Jul-2013
Complete Analysis Date : 30-Jul-2013
Date Issue : 30-Jul-2013

Sample Description : Natural Rubber Nipple
Analysis results :

Parameter	Units	Analysis Result	Standard Method/Technique/Equipment Used
Butyl Paraben	mg/kg	ND(<10)	HPLC
Ethyl Paraben	mg/kg	ND(<10)	HPLC
Iso-butyl Paraben	mg/kg	ND(<10)	HPLC
Methyl Paraben	mg/kg	ND(<10)	HPLC
Propyl paraben	mg/kg	ND(<10)	HPLC

Remark : -



Teem Chin Mean
Manager
M.Sc., AMIC,
A/2152/4620/04

CERTIFICATE OF ANALYSIS

MAIDAMAX (M) SDN BHD

Certificate No

: CN/nCML0179/0713



Photo of sample